
ANACONDA Minerals Co. uny **New Mexico Operations** P.O. Box 638 Grants, New Mexico 87020 Telephone 505 876 2211





CHAUG 2 A 9: 22

July 30, 1984

ALBUQUEAGUE, N.M.

Minerals Staff Rio Puerco Resource Area Bureau of Land Management 3550 Pan American Freeway, NE P.O. Box 6770 Albuquerque, NM 87107

Dear Sir:

The Second Quarter of 1984 sampling data for Anaconda's former Jackpile Minesite leases is submitted as follows:

- Radiological Analysis of Surface Water;
 Chemical Analysis of Surface Water;
- 3. Map showing Surface Water Sampling Locations;
- 4. Results of the Air Monitoring Program;
- 5. Results of the Ambient Radon Monitoring Study;
- 6. Map showing location of Air and Radon Monitoring Stations;
- 7. Map of Groundwater Monitoring Locations; and,
- 8. Chemical Analysis of Groundwater Monitoring, Second Quarter.

Sincerely,

Chief Environmental Engineer

Enclosures-8

pc: CES

CDW

MAS